



TOLERANCIAS A APLICAR CUANDO NO ESTÁ INDICADO. (Táchese la que no interese)
TOLERANCES TO APPLY IF NOT SPECIFIED. (Type what is not interested)

1000 > x	300 < x ≤ 1000	100 < x ≤ 300	30 < x ≤ 100	8 < x ≤ 30	x ≤ 8
+1.2	+0.8	+0.5	+0.3	+0.1	+0.05
-0.3	-0.2	-0.1	-0.05	-0.02	-0.01

SIGNOS SUPERFICIALES. SIGNOS SUPERFACES
3.2 / Mecanizado visible
0.8 / Mecanizado no visible
2.5 / Sin trabajar
12.5 / Mecaniz. apreciable tacto

h	Add dimensions catalog sheet	20-11-06	JMRG	MATERIAL: -	RDC
Version	Modification	Date	Name	MATERIAL:	
Created by:	Date	Name			
Dibujado:	16-09-26	Texidó			
Checked by:	16-09-26	Moscardó			
Revisado:					
FINISHING:					
ACABADO:					
WEIGHT:					
PESO:					
				MEZ BM REP BI D-AU AR	SCALE
				D-M D-HA BI MIX PU-W AR	Escala
				ADRW-0005A7176	1:2
				VERSION	SHEET Nº
				h	Hoja Nº
					4/4